Approved For Release 2006/04/18 : CIA-RDP82-00457R013700380008-5

CENTRAL INTELLIGENCE AGENCY

CLASSIFICATION

SECRET/CONTROL-U.S. OFFICIALS ONLY

25X1

NFORMATION REPORT REPORT N

CD NO. COUNTRY USSR (Black Sea) DATE DISTR. 10 September 1952 SUBJECT Ports of Kherson and Odessa NO. OF PAGES 3 25X1 DATE OF NO. OF ENCLS. 3 INFO. 25X1 PLACE SUPPLEMENT TO **ACQUIRED** REPORT: NO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFFMS OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVE-LATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON I PROHIBITED BY LAW. THE REPRODUCTION OF THIS FORM IS PROHIBITED.

as follows:

25X1

5X1

THIS IS UNEVALUATED INFORMATION

25X1

In the latter part of December 1951 Attachment 1 is a sketch of the por	25X1

- Grain elevator, in good working order. (1)
- A large three-or four-masted sailing vessel. According to [(2)25X1 this vessel was used as a naval school for officers of the or the Merchant Marine (it was not clear which).
- (3)A mole with dirt piled along its length.
- (4)A mole four meters wide, made entirely of wood.

(5)

- (6)Two small cranes with pipes and straps, loading coal.
- A crane moving on a track and carrying coal. The crane had a lifting capacity of about seven tons.
- (8) Open air coal storage space.
- (9)Railroad line with double tracks leading inland.
- (10) A 6,000-ton Bulgarian motorship. Later this ship was seen at Odessa (4 on Attachment 2).
- (11) Three small passenger ships.
- (12) A one-story building without a roof, used for coal storage.

CLASSIFICATION


STATE	х	HAVY	x	NSRB	DISTRIBUTION			ľ	
ARMY	x	AIR	x	FBI					

Approved For Release 2006/04/18: CIA-RDP82-00457R013700380008-5 SECRET/CONTROL-U.S. OFFICIALS ONLY (13) The customs house, a new one-story building. (14)A three-story building which houses the Harbor Master's office as well as some other offices. (15)Two cranes, in good working order, moving on tracks 25X1 25X1 25X1 (16)Shipyard district. these shipyards were constructed in 1951. Among other things, they are to construct a concrete floating dock every year. (17) Repair shops of the shipyard. (18) The chimney of the repair shop. (19) Four or five small buildings used by the shipyards. (20) A floating concrete dock under construction (the forms were being constructed). (21) A completed section of the floating dry dock at (20). (22) Two small steel vessels under construction. (23) Two small supporting frameworks, used in repairing small ships. $(24)^{\circ}$ A floating craft (sic). 25X1 25X1 this is used to house the workers of the shipyards. From Kherson. proceeded to Odessa, 25X1 25X1 in January 1952. Attachment 2 is a sketch of the port area and the numbers are identified as follows: Three 6,000-to 7,000-ton Soviet freighters, of German construction, undergoing repairs. (2)A floating dry dock. (3)Three old 6,000-to 7,000-ton Soviet freighters, undergoing repairs. A new Bulgarian freighter (motorship). This ship had been observed by source at Kherson (10 on Attachment 1). It was probably engaged in regular traffic between Odessa and Kherson. 25X1 (5) A railroad train. of cars, twelve of them were flatcars and each flatcar held 25X1 a motorboat made of steel without a keel. They were entirely electric-welded and the steel sheet metal was about 6 mm thick. Newly built, they were being unloaded from the flatcars and were probably destined to be used in rivers. The motorboats were 20 to 25 meters long, 3 to 3.5 meters wide, and less than 1.5 meters high (sic). Below is a sketch of the motorboat 25X1 and the key is as follows: An uncovered machine gun about 1.5 meters long, fixed on a base. There were holes about the middle of the barrel. Steel straps attached around the entire perimeter of the vessel in an oblique position. The straps had hooks at the end which were used for lifting or lowering the vessel.


- c. Small bridge
- d. Portholes
- e. Two propellers covered and fitted in such a way that they would not get damaged sitting on the freight car.

SECRET/CONTROL-U.S. OFFICIALS ONLY

25X1



On 22 January 1952 in the outer 25X1 harbor at Odessa a Soviet submarine coming out of the harbor 25X1 at about 0900 hours. It followed the course marked 2 on Attachment 3, and disappeared, heading south. 25X1 the submarine from a distance of 400 meters and it presented a curious phenomenon. It had neither turret now cannon; at the center of the submarine there was a funnel obliquely installed but no smoke was coming from it. 25X1 At about 1200 hours from the harbor and headed towards the Bosporus. following the course marked 3 on Attachment 3. At about the same time, a 7,000-ton Soviet freighter, 25X1 a fast vessel with a black stack, which had come out of the harbor that morning and was following the course marked 5 on Attachment 3. [25X1 From 6 it sailed to points 7, 8, and 9, and then disappeared. Between 1230 to 1300 hours, from positions 9 and 11, the submarine once again 25X1 at 12. It was following a northwest course (13 on Attachment 3) towards 10 and 13. The submarine and the freighter were approaching each other but suddenly the submarine began to submerge. 25X1 25X1 25X1 a rough drawing of the submarine when it surfaced, though 25X1 the submarine was not entirely above the surface of the sea. Only part of the submarine surface and the entire funnel were visible.



Attachments: Three

25X1 25X1

25X1

25X1


25X1

- Port of Kherson
- Port of Odessa
- Ship Routes Outside Odessa Harbor

SECRET/CONTROL-U.S. OFFICIALS ONLY

Attachment 1

PORT OF KHERSON




SECRET/CONTROL-U.S. OFFICIALS ONLY

Attachment 2


25X1

PORT OF ODESSA



Attachment 3 25X1

SHIP ROUTES OUTSIDE ODESSA HARBOR



SECRET/CONTROL-U.S. OFFICIALS ONLY